Assembly Instructions

MODEL: P317 (Round1200 x 760)


Thanks you for purchasing this quality product. Be sure to lay all components on a soft and clean surface before assembly in order to avoid components from being scratched.


CAUTIONS:

- 1. Check contents against list for quantity.
- 2. Familiarize yourself with the components and hardware by reviewing the Assembly Instructions.
- 3. Do not over tightened the screws and bolts as it may damage the threads.
- 4. Keep all hardware parts out of the reach of children.
- 5. Please "LIFT UP & MOVE" the table when ever you want to shift it.

	PARTS LIST				
NO.	DESCRIPTION	QTY			
1	TABLE TOP	1 PC			
2	LEG	2 PCS			

NO.	DESCRIPTION	QTY		
Α	JCBB M8 x 45mm	1 PC		
В	JCBC M6 x 40mm	4 PCS		
С	SPRING WASHER M8	1 PC		
D	FLAT WASHER M8	1 PC		
Ε	SPRING WASHER M6	4 PCS		
F	FLAT WASHER M6	4 PCS		
G	ALLEN KEY M5	1 PC		
Ξ	ALLEN KEY M4	1 PC		
	WOOD DOWEL	4 PCS		







COMPLETED ASSEMBLY

Insuructions

MODEL: P334 GT (Round850 x 400)


Thanks you for purchasing this quality product. Be sure to lay all components on a soft and clean surface before assembly in order to avoid components from being scratched.


CAUTIONS:


- 1. Check contents against list for quantity.
- 2. Familiarize yourself with the components and hardware by reviewing the Assembly Instructions.
- 3. Do not over tightened the screws and bolts as it may damage the threads.
- 4. Keep all hardware parts out of the reach of children.
- 5. Please "LIFT UP & MOVE" the table when ever you want to shift it.

	ia componente nom boing				
	PARTS LIST				
N	Ο.	DESCRIPTION	QTY		
•	1	GLASS TOP	1 PC		
. 2	2	LEG	2 PCS		

NO.	DESCRIPTION	QTY
Α	JCBC M6 x 35mm	1 PC
В	JCBC M6 x 40mm	4 PCS
С	SPRING WASHER M6	5 PCS
D	FLAT WASHER M6	5 PCS
Е	ALLEN KEY M4	1 PC







COMPLETED ASSEMBLY